



Figure 3. Connector Locations, Bottom View of Recorder/Reproducer

- b. On all models disconnect cable from input/output assembly to transport at J13 or J14 on electronics assembly (see Figure 3).
- c. Connect plug P1 of cable assembly (part no. 4051008-01) to jacks J13 or J14 on electronics assembly. (Use same plug that was referred to in step 6b.)
- d. Connect J1 of cable assembly (part no. 4051008-01) to plug P13/P14 on cable from input/output assembly.
- e. Connect P2 of cable assembly (part no. 4051008-01) into J2 on cue amplifier assembly.

Console Mounting of Cue Amplifier

To install the cue amplifier in a console-mounted ATR-100, proceed as follows:

1. Insure kit number is 4010319-AA.
2. Unplug power cable.
3. Remove console filler panel as follows: